

Brown Bag Topic for Wednesday, July 23, noon

## Lighting Technologies, Part 8

**Phone 1-888-422-7124, code 912410** (Please use mute, but don't use "hold")

Brown Bag Web site has visuals or links:

<http://www.bpa.gov/Energy/N/Utilities%5FSharing%5FEE/Utility%5FBrown%5FBag/>

Continue through the Lighting Technologies maze with Craig Ciranny

- <http://daltco.com/documents/Philips%20T8VHO%20Extreme%20Temp.%20System> **The Philips T8VHO 4' extreme temperature lamp: Is it a better choice than a T-5?**
- <http://www.nam.lighting.philips.com/us/ecatalog/fluor/pdf/p-5924.pdf> **T5HO 4' extreme temperature lamp**
- <http://www.nam.lighting.philips.com/us/ecatalog/fluor/pdf/p-5904.pdf> **T5VHO 4' extreme temperature lamp**
- <http://www.beghelliusa.com/downloads/pdf/BS105.pdf> **A 5' T5HO fixture**
- <http://www.maxlite.com/PDFs/FocusSheets/T8Lamp&BallastSystem.pdf> **Maxlite failures: Problems with their 4' high performance 3200 lumen lamp**
- **LED 4' Tubes: a record of spotty quality** <http://www.nichia.com/> <http://www.cree.com/index.asp> <http://www.lumileds.com/>

... and more